



459763



**POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 1 - SITE INFORMATION AND ASSESSMENT**

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

OH 040 000 7 202 68

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site)

NORTH AMERICAN CAR CORP.

02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER

3648 Hoffman Rd.

03 CITY

TOLEDO

04 STATE

OH

05 ZIP CODE

06 COUNTY

Lucas

07 COUNTY CODE

95

08 CONG DIST

09

09 COORDINATES LATITUDE

41° 42' 00" N

LONGITUDE

83° 30' 15"

Toledo Quadrangle

10 DIRECTIONS TO SITE (Starting from nearest public road)

From I-280 N, exit east onto Mahattan Blvd. After about 1 block, turn left (north) onto Hoffman Rd. The Chessie System RR Office Bldg will be on right approx 1/4 mile ahead.

III. RESPONSIBLE PARTIES

01 OWNER (If known)

Chessie System Railroad Co. (property)

02 STREET (Business, mailing, residential)

3648 Hoffman Rd.

03 CITY

Toledo

04 STATE

OH

05 ZIP CODE

06 TELEPHONE NUMBER

(419) 661-3057

07 OPERATOR (If known and different from owner)

North American Car Corp (renter)

08 STREET (Business, mailing, residential)

SAME

09 CITY

SAME

10 STATE

11 ZIP CODE

12 TELEPHONE NUMBER

()

13 TYPE OF OWNERSHIP (Check one)

☒ A. PRIVATE ☐ B. FEDERAL☐ C. STATE☐ D. COUNTY☐ E. MUNICIPAL☒ F. OTHER: Company filed for bankruptcy 12/15/84.☐ G. UNKNOWN

14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)

☐ A. RCRA 3001 DATE RECEIVED / /☐ B. UNCONTROLLED WASTE SITE (RCRA 103 c) DATE RECEIVED / /☒ C. NONE**IV. CHARACTERIZATION OF POTENTIAL HAZARD**

01 ON SITE INSPECTION

☐ YES

DATE

/ /

☒ NO

MONTH DAY YEAR

BY (Check all that apply)

☐ A. EPA☐ B. EPA CONTRACTOR☐ C. STATE☐ D. OTHER CONTRACTOR☐ E. LOCAL HEALTH OFFICIAL☐ F. OTHER:

(Specify)

CONTRACTOR NAME(S):

02 SITE STATUS (Check one)

☐ A. ACTIVE☒ B. INACTIVE☐ C. UNKNOWN

03 YEARS OF OPERATION

BEGINNING YEAR

ENDING YEAR

☒ UNKNOWN

04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED

unknown

05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION

unknown

V. PRIORITY ASSESSMENT

01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, complete Part 2 - Waste Information and Part 3 - Description of Hazardous Conditions and Incidents)

☐ A. HIGH

(Inspection required promptly)

☐ B. MEDIUM

(Inspection required)

☐ C. LOW

(Inspect on time available basis)

☐ D. NONE

(No further action needed, complete current disposition form)

VI. INFORMATION AVAILABLE FROM

01 CONTACT

David Ferguson

02 OF (Agency/Organization)

OEPA - NWDO / Hazardous Waste Division

03 TELEPHONE NUMBER

(419) 352-8461

04 PERSON RESPONSIBLE FOR ASSESSMENT

Ronald Boek

05 AGENCY

U.S. EPA

06 ORGANIZATION

E+E/FIT

07 TELEPHONE NUMBER

(312) 663-9415

08 DATE

09 24 85

MONTH DAY YEAR

040000720268



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER
OH OH000720268

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 ☐ A. GROUNDWATER CONTAMINATION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ B. SURFACE WATER CONTAMINATION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ C. CONTAMINATION OF AIR

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ D. FIRE/EXPLOSIVE CONDITIONS

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ E. DIRECT CONTACT

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ F. CONTAMINATION OF SOIL

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 AREA POTENTIALLY AFFECTED: _____

(Acres)

04 NARRATIVE DESCRIPTION

01 ☐ G. DRINKING WATER CONTAMINATION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ H. WORKER EXPOSURE/INJURY

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 WORKERS POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION

01 ☐ I. POPULATION EXPOSURE/INJURY

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: _____

04 NARRATIVE DESCRIPTION



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☐ J. DAMAGE TO FLORA
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ K. DAMAGE TO FAUNA
04 NARRATIVE DESCRIPTION (include name(s) of species)

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ L. CONTAMINATION OF FOOD CHAIN
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ M. UNSTABLE CONTAINMENT OF WASTES
(Spills/runoff/standing liquids/leaking drums)
03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

04 NARRATIVE DESCRIPTION

01 ☐ N. DAMAGE TO OFFSITE PROPERTY
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ P. ILLEGAL/UNAUTHORIZED DUMPING
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS


III. TOTAL POPULATION POTENTIALLY AFFECTED: _____

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references, e. g., state files, sample analysis, reports)

Potential Hazardous Waste Site
Preliminary Assessment

North American Car Corporation
Toledo, Ohio
OHD000720268



File

The North American Car Corporation rented property from the Chessie System Railroad Company located at 3648 Hoffman Rd., in the City of Toledo, Lucas County, Ohio. It is located in a remote area of Toledo, bordered on the north by the Hoffman Rd. Sanitary Landfill, which is an active landfill servicing the Toledo area. North American Car Corp. used the property they rented from Chessie to repair old railroad cars.

The history of North American Car Corp. is very sketchy. It is known that the company filed for bankruptcy in December, 1984. Investigative work done on this site failed to reveal any information concerning hazardous waste generation. Therefore, at this time, a preliminary assessment cannot be completed. The following is a list of people contacted during the course of the investigation:

State Files (Hazardous Waste, Solid Waste, Air, Industrial Wastewater, Public Water)

No information available

Dispatcher-Chessie System RR
3648 Hoffman Rd.

Informed me that North American Car Corp. rented property. Suggested contact is Mr. Bob Dusseau (419) 661-3057

Toledo Public Library
(419) 255-7055

Revealed that North American Car filed for bankruptcy 12/5/84. Also mentioned there was much merger activity in the prior 20 years.

Toledo Chamber of Commerce
(419) 243-8191

No information available

Ben Chamber, P.E. OEPA/NWDO

No information available

Paul Munn - Environmental Services
Toledo, OH (419) 693-0350

Neither he nor anyone else in department could supply any information on site.

Jerry Rotterdam - City Health
Dept./Toledo (419) 245-1732

No information available

Dr. Don Josif - U.S. EPA, Region V
(312) 886-0393

No information available

Since no records/documentation of any hazardous waste generation were discovered, no further action is recommended for FIT activity at this time. The OEPA should investigate this matter further therefore, a low priority is recommended for additional State action. One possible source would be **non** **non responsive**, who was referred to by the dispatcher at Chessie System Railroad. All previous attempts to reach him were unsuccessful.

